

Illustra Pro PTZ and i625 PTZ Firmware v2.1.2

Important Notice:

- This firmware is for both the Pro PTZ and i625ptz cameras
- If the camera is currently on 1.0.3 firmware or below, it will be necessary to first upgrade to 2.0.0.411 firmware before then installing 2.1.2 firmware
- Before upgrading your 625 PTZ outdoor cameras, please check the existing firmware version from either the camera web GUI or Illustra connect. If the FW revision is **1.0.1.A4491AA810** then contact level-three technical support. Any other FW revision please proceed with the upgrade
- We recommend upgrading one or two cameras first to become confident with the procedure, ensure that the upgrade process is not impacted by any unanticipated local factors, and to validate the upgrade procedure completes successfully in the working security environment. This best practice minimizes the risk a large number of mission cameras are impacted by the upgrade process due to any reason that might unexpectedly interfere with the successful completion of the procedure.

Firmware release 2.1.2 has the following improvements:

Enhancement to zoom and focus performance on Pro PTZ

Firmware Installation

Camera firmware can be installed using either Illustra Connect or the utility in the camera web interface.

NOTE: Insure your camera does not lose power during the firmware upgrade process. Please refer to the release notes for upgrade instructions.